

Date: Monday, August 07, 2000
To: CEC Customer
From: Yung Ho Park
Subject: DSD 412 Software Chips
Bulletin: No. 8

The DSD 412 software (PCU) labeled H829510 for chips U13 and U14 should fix the problem with the **F904** (low line fault) as well as the **F902** (power supply fault) and **F903** (line synchronization failure). All that needs to be done is to change out these chips, **no** need to write down parameters and to put them back in once the chips have been replaced. If you are experiencing these problems then contact Technical Support for new PCU chips.

Note: Make sure the DCU chips U39 and U40 have the latest software. These chips are designated **A205_4**. If the car has been running with these chips already, then do not change these chips and please return the ones that were sent.

Technical Support: (212) 489-5750 Fax: (212) 245-8245