

Date: Monday, August 07, 2000
To: CEC Customers
From: Wayne Locker
Subject: HPV 900

We have been informed by Magnetek that **all Power Interface Boards on the HPV 900 drive, with a revision number less than No. 6 must be replaced.** There is an intermittent problem with the gate firing circuit for the IGBT's. CEC personnel will be contacting you with the proper procedure for implementing the replacement. If you have any questions please do not hesitate to contact me at 212-397-0606.

Thank you