

Date: March 4, 1999
To: CEC Customer
From: Technical Support Department
Subject: Pre-torque compensation mode

We have discovered a problem with the PRE-TORQUE COMPENSATION feature on all SWIFT FUTURA controllers utilizing the DSD-412 SCR drive.

Please note: CEC has already resolved the problem and will be implementing the fix shortly. Until further notice the feature must be disabled.

Procedure to Disable Pre-Torque Compensation Feature

Log on to each individual controller and Re-Set CAR Control Status Word 8, Bit 9 and 11, by typing:

BITR8,9 <enter>

BITR8,11 <enter>

WRT <enter>

Thank you for cooperation.

If you require assistance with this bulletin please contact the Technical Support Department.