

Date: October 28, 1999
To: CEC Customers
From: CEC Technical Support Department
Subject: Proper Setting of Protective Features

In order to prevent certain conditions from occurring during specific modes of operation (such as run-time out errors and re-leveling) the following car CSW bits must be SET.

CS2 Bit 5 <BITS2,5> <WRT>

CS7 Bit 0 <BITS7,0> <WRT>

Please ensure that these bits are set on all SWIFT FUTURA controllers.

In the future these bits will be set internally by default, and will not be bit selectable.

Thank you for your cooperation.